

Handling MOS components

MOS components are extremely sensitive to static charges. Please observe therefore the following regulations:

1 Components sensitive to static charges are always shipped in protective package. On the packages you find the subsequent symbol:



2 Avoid any contact of components with metal parts and foils made of metal or similar chargeable materials.


3 Don't touch the connector pins when your wrist is not grounded with a conducting wristband.

4 Use a ground connection when working with sensitive components.


5 Never plug or unplug PCBs containing sensitive components when the machine is switched on.

Subject to change
Copyright by WILLI STUDER AG
Printed in Switzerland
Order No. 10.30.1000 (Ed.1188)

REAR



TO LEFT SIDE




PREAMPLIFIER 1.725.265.00


INPUT-OUTPUT UNIT 1.725.245.00

PHONO UNIT 1.725.255.00


RIGHT SIDE






TO LEFT SIDE



INTERCONNECTION
UNIT 1.725.285.00

REAR
**INPUT-OUTPUT UNIT
1.725.245.00**
TO
RIGHT
SIDE
POWER AMPLIFIER 1.725.275.00

**MAINS TRANSFORMER
1.725.205.00**

POWER SUPPLY UNIT 1.725.235.00

**INTERCONNECTION
UNIT 1.725.285.00**
TO
RIGHT
SIDE
MICROCOMPUTER BOARD 1.725.295.00
FRONT